## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE OFFICE OF CERTIFICATE OF CORRECTION

Patent No.: 7,078,011

Application No.: 10/812,084

Inventors: Morrow et al.

Issue Date: July 18, 2006

Title: METHOD OF SUPPLYING HYDROGEN TO A PIPELINE

> Statement in Support of a Request for Certificate of Correction to Correct Inventorship in Patent Under Rule 37 CFR 1.324

Attention: Certificate of Correction Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

- I. Rommel Marquis Oates state:
- I reside at Houston in the State of Texas and am a citizen of the United States.
- 2. I have a post office address at 810 Forest Bark Lane, Houston, Texas 77067.
- The inventorship error of failing to include Rommel Marquis Oates as an inventor
  of the patent, referenced above, occurred without any deceptive intention on the part of
  myself, Rommel Oates.

Respectfully submitted.

A Danskin Calas

Date: 6/18/2009